



Pericom Semiconductor Corp. • 3545 North First St. • San Jose, CA 95134 • USA

PRODUCT DISCONTINUANCE NOTIFICATION (PDN)

PDN Number: #[10-1103](#)

Issue Date: [Dec. 8, 2010](#)

Product(s) Affected: **VCXO products:**

- 1) [ST1317BBB-65.5360 \(079-01286-0000\)](#) aka: [FR6550004](#)
Pericom recommended replacement part: [FR6550007](#)
- 2) [ST1317BAB-49.4080 \(079-01279-0000\)](#) aka: [FR4940001](#)
Pericom recommended replacement part: [FR4940002](#)
- 3) [ST1307BAB-19.4400 \(079-01245-0000\)](#) aka: [FR1940004](#)
Pericom recommended replacement part: [FR1940007](#)

Last Purchase Date: [5/31/2011](#)

Last Shipment Date: [8/31/2011](#)

Reason for Discontinuing Listed Products:

- Obsolete Design/Process Technology
- Obsolete Package/Assembly Technology
- No current or rapidly declining sales
- Other: Manufacturing capability no longer available

See Product List Attachment: Yes; No

Pericom Contact: [Raul Aman](#)

Title: [Sr. Quality Manager](#)

Phone: [408 435-0800, Ext 217](#)

Fax: [408-435-1100](#)

eMail: raman@pericom.com

*** Note:**

Pericom apologizes for any inconvenience this situation may cause our customers. It is recommended that customers should contact their Pericom sales representative as soon as possible to discuss how Pericom can support customer needs with the recommended Fit, Form and Function replacement part as indicated above.

Customer Acknowledgement:

Customer:

Name:

Title:

Date:

E-Mail:

Phone:

Fax:

Customers may use this form to acknowledge receipt of this notification, or can e-mail the Pericom contact noted above.

Customer Comments: