

## Customer Notification of Product/Process Changes

Page: 1/1

*0001	A1 -	DC01	0000
*PCN	INO.:	PCN	-いといり

\*Issued Date: 2020/3/24

\*Subject: Due to Coronavirus (COVID-19) and Exhaust pipe burned out on Mar-11

to Cause WMEC 4" Fab Wafer Shortage

Qualification of Alternative SGPP Wafer Sources for Bridge Rectifier Products

\*Implement schedule: 2020/May/1st

\*Affected category: Die size coverage 40-180mil

\*Affected Product: GPP Bridge

Change Item	☐ Material ☐ Design ☐ Process	Others : Bridge 4" wafer source	
Impact Item	1. Product P/N :	3. Label : ☐ Yes ■ No	
	2. Marking : □Yes ■ No	4. Other items ∶ ☐ Yes ■ No	
Related Item	As attachment list		
Change Purpose	Solve WMEC 4" SGPP Wafer shortage	issue to add Anhui Anxin 4" SGPP wafer source	
	Existed Fab	Alternative Fab	
Description of Change	Manufacture site: WMEC 4" Fab	Manufacture site: Anhui Anxin 4" Fab WMEC 4" Fab	
	■ Electrical Test Report	■ SGS / MCD_MDS Report	
Related Report	■ ESD Report	■ Mechanical Test Report	
	□Others		
Sample availability	□Yes ■No		
Customer	☐ Approve		
Approval	☐ Disapprove	e	
Customer			
Requirement			
(ex. Last Buy		•	
requirement)			

- 1.If you need sample(s) or any question, please contact with our Salesperson within 30day
- 2.LSC will follow WW industry standard spec (JESD46D) criteria define as below.
- A. Customers should acknowledge receipt of the PCN within 30 day period constitutes
- B. Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change.
- C. After acknowledgement, lack of additional response within the 90 day period constitutes acceptance of the change.
- D. If customer requires additional time to perform samples testing, beyond the 90 day review period an extension must be negotiate

**Product LOB**