



Pericom Semiconductor Corp. • 3545 North First St. • San Jose, CA 95134 • USA

PRODUCT DISCONTINUANCE NOTIFICATION (PDN)

PDN Number: #10-0501

Issue Date: May 10, 2010

Product(s) Affected: **Quartz Crystal Tuning Fork:**

32S12C-F (in Tape & Reel: 32S12C-F(T))

Alternative Supply Sources: Recommended Alternatives:

Contact your local Pericom Sales representative to discuss the G4 Series Quartz Crystal (G43270009)

Last Purchase Date: June 15, 2010

Last Shipment Date: September 15,

Reason for Discontinuing Listed Products:

- Obsolete Design/Process Technology
- Obsolete Package/Assembly Technology
- No current or rapidly declining sales
- Other: Manufacturing capability no longer available (see below)

See Product List Attachment: Yes; No

Pericom Contact: Brian Conway

Title: Director of Quality

Phone: 408 435-1100, Ext 314

Fax: (408) 321-0324

eMail: bconway@pericom.com

*** Note:**

The 32S12C-F & 32S12C-F(T) will no longer be available in the near future; therefore discontinuation of this product must be implemented quickly. Pericom apologizes for any inconvenience this situation may cause our customers, but unfortunately the normal last time purchase & last time shipment periods can not be offered. It is recommended customers should contact their Pericom sales representative as soon as possible to place last time purchases, and discuss how Pericom can support customer needs with the recommended Fit, Form and Function replacement G4 Series Quartz Crystal Tuning Fork (G43270009)

Customer Acknowledgement:

Customer:

Name:

Title:

Date:

E-Mail:

Phone:

Fax:

Customers may use this form to acknowledge receipt of this notification, or can e-mail the Pericom contact noted above.

Customer Comments: